



MOLDIS

mould and die sets

AG 7500

150

 S mm		 Ø150 L1=178 L1=178 L1=178		 Ø150 L1=205 L1=236 L1=255	 Ø150 L1=255		 Ø150 L1=270
S mm							
 L1 mm							
МОДЕЛЬ		CW 9500 CW 11800 KT 9500		GN 7500 CM 10000 CD 9600	AG 7500		CS 18300


ВАРИАНТЫ КРЕПЛЕНИЯ

	Вставка	Верхнее крепление	Базовое крепление	Нижнее крепление	Поддерживающее крепление
					
КАК ЗАКАЗАТЬ		A14-150  581 A34-150  583	B16-150  591 B21-150  591 B76-150  595	C05-150  597 C20-150  599	D02-150  601 D67-150  603

ВАРИАНТЫ ЗАЩИТЫ

Увеличьте срок службы ваших газовых пружин за счет использования защитных решений от суровых условий работы (например, горячей штамповки), специально разработанных для минимизации воздействия твердых или жидких загрязняющих веществ и продления срока службы газовых пружин.

Приспособление для чистки (PW)



PW не предполагает каких-либо изменений размеров газовой пружины. Полезный ход остается таким же, как номинальный ход.



Приспо-
собление
для чистки

